

Accidents between dates 01/01/2010 and 31/12/2019 (120) months

Selection: Notes:

Selected using Manual Selection

I08230310 20/03/2010 Time 1600 Vehicles 1 Casualties 1 Slight
E: 604071 N: 214223 First Road: U Road Type Single carriageway
Speed limit: 40 Junction Detail: Not within 20m of junction Not applicable
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Daylight: no street lighting Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Slippery road (due to weather)	Vehicle 1	Very Likely	
2nd: Loss of control	Vehicle 1	Very Likely	
3rd: Sudden braking	Vehicle 1		
4th:			
5th:			
6th:			

RIDER OF VEH 1 WAS TRAVELLING ALONG EAST MERSEA RD TOWARDS EAST RD. HE LOST CONTROL OF THE VEH AS HE APPLIED THE BRAKES, SKIDDED AND COLLIDED WITH THE WELCOME TO MERSEA SIGN.

Occurred on EAST RD 200M WEST J/W REWSALLS LAWS

Vehicle Reference 1 Motor Cycle over 50 cc and up to 125cc Going ahead right bend
Vehicle movement from W to E No tow / articulation
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: Road sign / ATS
Nearside Age of Driver 19 Male
Not hit and run Breath test Negative
Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 19 Male Driver/rider Severity: Slight
Not a pupil Postcode Seatbelt

Accidents between dates 01/01/2010 and 31/12/2019 (120) months

Selection: Notes:

Selected using Manual Selection

I17660611 14/06/2011 Time 1735 Vehicles 2 Casualties 1 Serious
E: 604965 N: 214402 First Road: U Road Type Single carriageway
Speed limit: 40 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight: no street lighting Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to judge other persons path or speed	Vehicle 001	Very Likely	
2nd: Sudden braking	Vehicle 001	Very Likely	
3rd: Loss of control	Vehicle 001		
4th:			
5th:			
6th:			

V1 & V2 TRAVELLING EAST ON EAST ROAD. V2 AHEAD OF V1 SLOWS AND COMES TO A HALT WAITING TO TURN RIGHT. V1 FAILS TO SLOW UNTIL LAST MINUTE WHEN BRAKES TOO HEAVY AND LOSES CONTROL. V1 RIDER DISMOUNTS AND V1 COLLIDES WITH REAR OF V2.

Occurred on EAST ROAD, EAST MERSEA J/W CHURCH LANE.

Vehicle Reference 1 Motor Cycle over 125 cc and up to 500cc Going ahead other
Vehicle movement from W to E No tow / articulation
On main carriageway Skidded
Location at impact Jct Approach First impact Front Hit vehicle: 002
Hit object in road None Off road: None
Did not leave carr Age of Driver 17 Male
Not hit and run Breath test Negative
Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 17 Male Driver/rider Severity: Serious
Not a pupil Postcode Seatbelt

Vehicle Reference 2 Car Waiting to turn right
Vehicle movement from W to E No tow / articulation
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 70 Female
Not hit and run Breath test Negative
Driver Postcode: VRM:

Accidents between dates 01/01/2010 and 31/12/2019 (120) months

Selection: Notes:

Selected using Manual Selection

I00700114 11/01/2014 Time 0855 Vehicles 2 Casualties 1 Serious
E: 604970 N: 214401 First Road: U Road Type Single carriageway
Speed limit: 60 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Dazzling sun	Vehicle 001	Very Likely	
2nd: Failed to look properly	Vehicle 001	Possible	
3rd:			
4th:			
5th:			
6th:			

VEHICLE 1 APPROACHING THE JUNCTION OF CHURCH LANE, WHILST DRIVING ALONG EAST ROAD TOWARDS EAST MERSEA BEACH. VEHICLE 2 TRAVELLING ALONG EAST ROAD TOWARDS COLCHESTER. AT THE JUNCTION WITH CHURCH LANE, VEHICLE 1 HAS TURNED RIGHT INTO THE PATH OF VEHICLE 2.

Occurred on EAST ROAD, JUNCTION WITH CHURCH LANE, EAST MERSEA.

Vehicle Reference 1 Car Turning right
Vehicle movement from W to S No tow / articulation
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or 1 First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 36 Male
Not hit and run Breath test Negative
Driver Postcode: VRM:

Vehicle Reference 2 Car Going ahead other
Vehicle movement from E to W No tow / articulation
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or 1 First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 60 Female
Not hit and run Breath test Negative
Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 60 Female Driver/rider Severity: Serious
Not a pupil Postcode Seatbelt

Accidents between dates 01/01/2010 and 31/12/2019 (120) months

Selection: Notes:

Selected using Manual Selection

I18700614 10/06/2014 Time 1705 Vehicles 3 Casualties 1 Slight
E: 603878 N: 214184 First Road: U Road Type Single carriageway
Speed limit: 40 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Nervous/Uncertain/Panic	Vehicle 1	Very Likely	
2nd: Failed to judge other persons path or speed	Vehicle 1	Very Likely	
3rd: Sudden braking	Vehicle 1	Very Likely	
4th: Loss of control	Vehicle 1	Very Likely	
5th:			
6th:			

VEH 1 AND 2 WERE TRAVELLING TOWARDS WEST MERSEA. VEH 3 WAS TRAVELLING TOWARDS EAST MERSEA. VEH 1 OVERTOOK VEH 2 ON APPROACH TO A RIGHT HAND BEND. VEH 3 APPROACHING THE SAME BEND FROM THE OPPOSITE DIRECTION. THE RIDER OF VEH 1 CATCHES SIGHT OF VEH 3 THEN PANICS, BRAKES THEN LEAVES THE CARRIAGEWAY NEAR SIDE AND DISMOUNTS CAUSING SLIGHT INJURY..

Occurred on EAST MERSEA ROAD EAST MERSEA, AT THE J/W REWSALL'S LANE

Vehicle Reference 1 Motor Cycle over 125 cc and up to 500cc Going ahead left bend
Vehicle movement from E to NW No tow / articulation
On main carriageway Skidded
Location at impact Jct Approach First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Nearside Age of Driver 22 Male
Not hit and run Breath test Negative
Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 22 Male Driver/rider Severity: Slight
Not a pupil Postcode Seatbelt

Vehicle Reference 2 Car Going ahead other
Vehicle movement from NW to E No tow / articulation
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 20 Male
Not hit and run Breath test Negative
Driver Postcode: VRM:

Vehicle Reference 3 Car Going ahead right bend
Vehicle movement from NW to E No tow / articulation
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 56 Male
Not hit and run Breath test Negative
Driver Postcode: VRM:

Accidents between dates 01/01/2010 and 31/12/2019 (120) months

Selection: Notes:

Selected using Manual Selection

16109408 13/08/2016 Time 1100 Vehicles 2 Casualties 1 Slight
E: 606049 N: 215040 First Road: U Road Type Single carriageway
Speed limit: 60 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Vehicle 1	Very Likely	
2nd:			
3rd:			
4th:			
5th:			
6th:			

I WAS CYCLING WITH A GROUP OF FRIENDS EASTERLY ALONG EAST ROAD. THE COACH CAME ROUND THE CORNER FROM THE OTHER DIRECTION. THE ROAD IS NARROW BUT THE COACH FAILED TO SLOW DOWN AND FAILED TO PULL OVER TO GIVE THE CYCLISTS ENOUGH ROOM. A COUPLE OF CYCLISTS AHEAD OF ME JUST MANAGED TO SQUEEZE THROUGH BUT THE SIDE OF THE COACH HIT MY HANDLEBARS AND KNOCKED ME OFF MY BIKE. I COULD EASILY HAVE FALLEN UNDER THE REAR WHEELS OF THE COACH. I HAVE SUFFERED CUTS AND BRUISES AND CRACKED RIBS. THERE IS ALSO DAMAGE TO MY BIKE. MY CYCLING JERSEY IS TORN FROM CONTACT WITH THE BUS AND HAS THE GREEN PAINT OF THE BUS ON IT. I CAN PRODUCE THIS IF REQUIRED. I HAVE PHOTOS OF MY INJURIES AND THE ROAD WHICH I CAN EMAIL TO YOU IF REQUIRED. THE MAIN REASON FOR FILING THIS REPORT

Occurred on EAST ROAD EAST MERSEA UNSPECIFIED ROAD OR LOCATION BROMANS LANE

Vehicle Reference 1 Bus or coach Going ahead other
Vehicle movement from NE to SE No tow / articulation
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 38 Male
Hit and run Breath test Driver not contacted
Driver Postcode: VRM:

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from W to E No tow / articulation
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 66 Male
Not hit and run Breath test Not applicable
Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 66 Male Driver/rider Severity: Slight
Postcode Seatbelt

Accidents between dates 01/01/2010 and 31/12/2019 (120) months

Selection: Notes:

Selected using Manual Selection

17177280 30/04/2017 Time 2300 Vehicles 1 Casualties 4 Slight
E: 603827 N: 214201 First Road: U Road Type Single carriageway
Speed limit: 60 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: no street lighting Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation			
	Factor:	Participant:	Confidence:
1st:	Loss of control	Vehicle 1	Very Likely
2nd:	Exceeding speed limit	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEHICLE ONE WAS PROCEEDING ALONG EAST ROAD, EAST MERSEA IN THE GENERAL DIRECTION OF THE STROOD. VEHICLE ONE LOST CONTROL AND COLLIDED INTO A BRICK WALL BELONGING TO 1 WEIR FARM, EAST ROAD.

Occurred on 1 WEIR FARM EAST ROAD UNSPECIFIED ROAD OR LOCATION 40 METRES EAST OF JUNCTION V

Vehicle Reference 1 Car Going ahead other
Vehicle movement from NE to SW No tow / articulation
On main carriageway Skidded and overturned
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
O/S Age of Driver 18 Male
Not hit and run Breath test Negative
Driver Postcode: VRM:

Casualty Reference:	1	Vehicle:	1	Age:	18	Male	Driver/rider	Severity:	Slight
				Postcode			Seatbelt		
Casualty Reference:	2	Vehicle:	1	Age:	17	Female	Passenger	Severity:	Slight
				Postcode			Seatbelt		
							Front seat		
Casualty Reference:	3	Vehicle:	1	Age:	17	Female	Passenger	Severity:	Slight
				Postcode			Seatbelt		
							Back seat		
Casualty Reference:	4	Vehicle:	1	Age:	17	Male	Passenger	Severity:	Slight
				Postcode			Seatbelt		
							Back seat		

Accidents between dates 01/01/2010 and 31/12/2019 (120) months

Selection: Notes:

Selected using Manual Selection

18330852 26/09/2018 Time 2320 Vehicles 1 Casualties 1 Slight
E: 603720 N: 214249 First Road: U Road Type Single carriageway
Speed limit: 40 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: no street lighting Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Impaired by alcohol	Vehicle 1	Very Likely	
2nd: Impaired by drugs (illicit or medicinal)	Vehicle 1	Very Likely	
3rd:			
4th:			
5th:			
6th:			

VEHICLE ONE TRAVELLING EAST ALONG EAST ROAD N THE GENERAL DIRECTION OF CUDMORE GROVE. THE DRIVER OF VEHICLE ONE HAS LEFT THE CARRIAGEWAY BY THE NEAR SIDE COLLIDING WITH A WOODEN TELEGRAPH POLE DESTROYING IT BEFORE OVERTURNING THE VEHICLE ENDING UP IN A FIELD. DRIVER OF VEHICLE ONE ARRESTED FOR FAILING THE ROADSIDE BREATH TEST, AND DRUG TEST.

Occurred on EAST ROAD NEAR JN WITH REWSALLS LANE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from W to E No tow / articulation
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: Telegraph / Electricity pole
Nearside Age of Driver 22 Male
Not hit and run Breath test Positive
Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 22 Male Driver/rider Severity: Slight
Postcode Seatbelt

Accidents between dates 01/01/2010 and 31/12/2019 (120) months

Selection: Notes:

Selected using Manual Selection

19834744 28/04/2019 Time 0937 Vehicles 1 Casualties 1 Slight
E: 603304 N: 214232 First Road: U Road Type Single carriageway
Speed limit: 40 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Poor or defective road surface	Vehicle 1	Possible	
2nd:			
3rd:			
4th:			
5th:			
6th:			

V1 WAS TRAVELLING IN THE GENERAL DIRECTION OF COLCHESTER. IT WAS TRAVELLING AT APPROXIMATELY 30MPH. V1'S FRONT WHEEL HAS BECOME UNBALANCED AS IT CROSSED OVER A RUT IN THE ROAD. THIS HAS CAUSED V1 TO FLIP ONTO ITS NEAR SIDE AND DOWN INTO A DITCH BORDERING THE CARRIAGEWAY. THE RIDER OF V1 HAD THE TRIKE FALL OVER HER.

Occurred on EAST MERSEA ROAD - 136 METRES FROM JUNCTION WITH UNCLASSIFIED ROAD

Vehicle Reference 1 Motorcycle over 500cc Going ahead other
Vehicle movement from E to W No tow / articulation
On main carriageway Skidded and overturned
Location at impact Not at, or within 20M of Jct First impact Near side Hit vehicle:
Hit object in road None Off road: None
Near side Age of Driver 62 Female
Not hit and run Breath test Negative
Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 62 Female Driver/rider Severity: Slight
Postcode Seatbelt

Accidents between dates 01/01/2010 and 31/12/2019 (120) months

Selection:

Notes:

Selected using Manual Selection

Accidents involving:

	Fatal	Serious	Slight	Total
Motor vehicles only (excluding 2-wheels)	0	1	2	3
2-wheeled motor vehicles	0	1	3	4
Pedal cycles	0	0	1	1
Horses & other	0	0	0	0
Total	0	2	6	8

Casualties:

	Fatal	Serious	Slight	Total
Vehicle driver	0	1	2	3
Passenger	0	0	3	3
Motorcycle rider	0	1	3	4
Cyclist	0	0	1	1
Pedestrian	0	0	0	0
Other	0	0	0	0
Total	0	2	9	11